





NRA HD 16 Temporary Safety Measures Inspections

Alastair de Beer Project Manager (Safety) National Roads Authority

National Roads Authority - Standards Section Training for New Developments April 2013





What is NRA HD 16

- Temporary Safety Measures Inspections
- In other words Traffic Management Inspections by the Road Authority
- Deals with Safety at Road Works for primarily <u>road users</u> and also road workers.







Why NRA HD 16?



- EU Road Infrastructure Safety Management Directive 2008/96/EC (S.I. No. 472/2011) requires that an <u>inspection regime be implemented</u> by Member States.
- This Directive applies to roads which are part of the trans-European road network (TERN).
- In Ireland Temporary Safety Measures Inspections are required on <u>all National Roads</u>



Current Guidance



- Best practice on implementation of traffic management measures included in:
- <u>Chapter 8</u> of the Traffic Signs Manual, and,
- Guidance For The Control And Management Of Traffic At Road Works
- > (aka the Ashbourne document)



Who does the Inspections?



Who undertakes the inspection	Temporary Safety Measures
National Roads Authority	Projects procured by the National Roads Authority
Local Authority	Projects sanctioned and/or procured by the Local Authority
Statutory undertaker/road operator (e.g. PPP)	Projects under their management.



Role of the Road Authority (Local Authority)

Periodic inspections of temporary safety measures at roadwork sites are carried out on all projects <u>sanctioned and/or procured</u> by them, to confirm that the Requirements are being implemented



Frequency of Inspections

Duration of Road Works	n of Road % of sites to be inspected per annum			
Exceeding 1 year in duration	100% of sites to be inspected	Quarterly		
1 month to 1 year in duration	30% to 40% of sites to be inspected	Twice per year		
Greater than 1 day, less than 1 month	10% to 20% of sites to be inspected	Single Inspection		
1 day in duration	Random	Single Inspection		





Role of Local Authority and Utility Companies

- Local Authorities should advise any person or body undertaking roadworks on their roads (eg. <u>Road Opening</u> <u>Licensee</u>), that this Directive is now in place
- <u>Utilities to inspect their own sites</u> in accordance with the Guidelines,





Role of the Authority (NRA)



 Prepare Web-based database to track all roadworks on National Roads
 Carry out random inspections of Local Authority and statutory undertaker's Temporary Safety Measures inspection systems.







How to Notify the NRA?





- Registered by Project Manager in Local Authority
- Notification to be done prior to commencement of construction

















🏉 NRA Map Portal - Windows I	nternet Explorer						- 2 ×
)80/maps/Works/Create/01e3e245	-8d75-435a-abbb-b53efe58574	40	💌 🗲 🗙 🙋 Bing			P -
File Edit View Favorites Tool	ls Help						
🗙 🍖 Convert 👻 🛃 Select							
🚖 Favorites 🛛 🚖 🙋 Captial Work	ks Management 🏉 Suggested	l Sites 🔻 🙋 Free Hotmail 🙋	Get more Add-ons 🔹				
🚧 NRA Map Portal				👌 🔹 🗟 🕤 🖶) ▼ Page ▼ S	Safety 👻 T	ools 🕶 🔞 🕶 👋
	below.						^
Contractor Contact	Contractor 10						
Contractor Email	swhelan@dataworks.ie						
Contractor Phone	051878555						
PSCS Contact Name	pl	-					
PSDP Contact Name	PSCS 1 PSCS 10						
HSA AF1 Submitted?	PSCS 12	×					
	PSCS 13	3een Submitted					
	PSCS 14	Authority					
Static	PSCS 15						
✓ Mobile	PSCS 16						
Diversion							
							~
http://nradev2:1080/maps/Works/Creat	te/01e3e245-8d75-435a-abbb-b53	efe585740#		Secol intra	net	- @	🔍 100% 🔹 💡

🖉 NRA Map Portal - Windows Internet Explorer		- 7 🛛
The second seco	🖌 🗲 K 🕒 Bing	P •
File Edit View Favorites Tools Help		
🗙 🎭 Convert 👻 🔂 Select		
🚖 Favorites 🛛 🚔 🔊 Captial Works Management 🏈 Suggested Sites 🝷 🖉 Free Hotmail 🖉 Get more Add-ons 🝷		
MRA Map Portal	🏠 🔹 🔝 🕤 🖃 🖶 👻 Page 🗸 Safety 🔹	• Tools • 🕢 *
Map Portal Home Collisions Works -		Sign Out

Worklist

Works in Progress							
#	Route	Description	Feature	Contractor	Start/Finish		
191	Placeholder While Testing	M9 test AdB	LineString	Contractor 11	28/03/2013 - 17/04/2013	Update	View
212	Placeholder While Testing	M6 Relining of Motorway	Point	Contractor 10	08/04/2013 - 23/04/2013	Update	View

🖓 🔹 🔍 100% 🔹

•	http://nradev2:1080/maps/Works/All	Works		¥ +7	X Bing	
Edit	View Favorites Tools Help					
Conve	vert 👻 🔂 Select					
vorites	👍 💋 Captial Works Management	🏉 Suggested Sites 👻 🔊 Free Hotm	ail 🖉 Get more /	Add-ons •		
RA Map I					🔹 🔊 - 🖃 🖶 - Page - Safe	ety 🕶 Tools 🕶 🌀
	, ortai					
ap F	Portal Home Collisions	Works -				Sign Ou
		Мар				
w.	orklist	Map Worklist				
W	orklist	•				
	orklist ks in Progress	Worklist All Works	7			
		Worklist	s Feature	Contractor	Start/Finish	
Wor	ks in Progress	Worklist All Works Works Currently In Progres		Contractor Contractor 11	Start/Finish 28/03/2013 - 17/04/2013	View
Wor #	Route Placeholder While Testing	Worklist All Works Works Currently In Progres	Feature			View

🖓 🔹 🔍 100% 🔹



 (\Rightarrow)

4





Example of Inspection form used by NRA



N				RY SAFETY MEA		ES (T	SM)			
	CIRKS LOCA TION COOPEDIN	ATES		FOUTE NUMBER:		READ	UTHOR	TY:		
START:	Location Plan Attached	END		Reacommen Co. Co.						
READW	CHARLES START DATE:		EXPECTED ON THE	OF DOMPLETION OF ROADW	OFBCS:					
121020	12	12	1611/12(Beller to)	Resconston Co. Co. without	61 T				8	
CONTRA	ACTOR (Famplicable)	TSM DESIGNED	8	FICA DWORKS TYPE (C	onstuck	on/ Non-	Construct	Sont:		
NEI				Emergency Works						
25235		PSDP:		ROADWORKS SAFETY	OFFICE	B/ CODE	TIMA TO	92-	-	
NEL .		NR .								
Contect!	Details:	Contact Details:		Contact Datalia:						
NFI .	NE NE		101							
Dep-cp	A DESCRIPTION OF THE R. P. C.	1000		1.1						
			establed TM. This n Defailes	aport raiatas lo sita obsar o and openated appropriate	ations	anly.			_	
	ant Required	0		nol quinte squirig inprove		_				
Incort		the second se	Conditions sequiting	immediate consultive/ improv	arment ac	tion.			_	
NET Pare	beend	NR	Harn rol reviewed d	uring inspection.				10	-	
TEM	Temporary Salety Mea	ISURAS (TISIA) FOR	Roadworks		MB		0	G	Arrest	
TSM 1				and showing called in the second s				_		
-	Does the Design contor installed conform to the Have all hazards been re Has allowance been me	design layout and essessed in the TS	parameters?	and does the TSM's	1					
ISMA	been adequately signed Have Cardal been infor	17					_	*		
TSNE	Have Cardal been infor works?	med of speed limit	s being introduced	for the duration of the						
1947	Are all traffic managem understood be the gene Manual (Le, strafheight)	rai road user) and	in accordance with					1		
TSN I		condance with the	requirements of th	e TSM and are sightline: the road, parked		0				
1394.0	Will the site be safe dur	ing hours of darkin	ess and adverse v	salitier conditions?						
24, 10	is the carriagoway/looks	ray being kept clea	and surpland surpland	lus equipment?	2.0	1.1	12		2	
11.461	Are materials/plant com	octly and safely siz	rad?							
120 12	is there sale accessing	rass to adjacent pr	valo premises an	bcal roads unclore?			126			
150.13	Does signing and guard	ing meet the chan	ging site condition	6 ?			100		1.0	
1584.14	And the life continue increases	perments working a	Their optimum law	el lo reduce traffic	1 3	8	8			
TSN. 15	Are all misleading parm Have all signs been por public?	stioned correctly to	eliminate a poter	tial hazard to the general	2		÷ .			
1504.16	Have the needs of pede pedestrians, blind, cyclic public routes have been	sis, horses etc) be blocked, has suit	en addressed in t able allematives b	e layout? If existing			_			
	is the Work Area dearly									







Photo TSM 2

Photo TEM 5

Summary of lenge-clien: Approach from Cablety : Photo TSM + Lacommin Cablety : Photo TSM + Lacommin Cablety is a Closed signage with supplementary plate. TM sheed tearlies had here to slow lano(fast area and here a device of closed and them slow signage with supplementary plate. TM sheed tearlies that here to slow lano(fast Photo TSM = Lacommin Chable Lane Closed signage with supplementary plate. Photo TSM = Lacommin Chable Lane Closed signage with supplementary plate. Photo TSM = Lacommin Chable Lane Closed signage with supplementary plate. Photo TSM = Lacommin Chable Lane Closed signage with supplementary plate. Photo TSM 5 - Lacommin Chable Lane Closed signage with supplementary plate. Photo TSM 5 - Lacommin Chable Lane Closed signage with supplementary plate. Photo TSM 5 - Lacommin Chable Lane Closed signage with supplementary plate. Photo TSM 5 - Lacommin Chable Lane Closed signage with supplementary plate. Photo TSM 5 - Lacommin Chable Lane Closed signage with supplementary plate. Photo TSM 5 - Lacommin Chable Lane Closed signage with supplementary plate. Photo TSM 5 - Lacommin Chable Lane Closed signage with supplementary plate. Photo TSM 6 - Lacommin Chable Lane Closed signage with supplementary plate. Photo TSM 6 - Lacommin Chable Lane Closed signage with supplementary plate. Photo TSM 6 - Lacommin Chable Lane Closed signage with supplementary plate. Photo TSM 6 - Hard shoulder typer. Cores in type appear to be approx. an of c. Table 6.3.5 of Chapter a recommends 1.5m ofc.

TSM	Temporary Safety Measures (TSM) for Roadworks	N/R	R	0	G	Average
TSM.1	Evidence available that sufficiently trained staff are present to design and implement the TSM?	x				
TSM.2	Does the Design conform to the Traffic Signs Manual (DoT) and does the TSM's installed conform to the design layout and parameters?	x				
TSM.3	Have all hazards been assessed in the TSM?	x				
TSM.4	Has allowance been made for the delivery and removal of materials, and have these been adequately signed?				x	
TSM.5	Have Gardai been informed of any traffic lights or stop/go system in use?	X				
TSM.6	Have Gardai been informed of speed limits being introduced for the duration of the works?	x				
TSM.7	Are all traffic management equipment in good condition/fit for purpose (easily understood be the general road user) and in accordance with the Traffic Signs Manual (i.e. size/height, colour, reflectivity)?		x			
TSM.8	Are sign sightlines in accordance with the requirements of the TSM and are sightlines adequate for all other signs (i.e. free from bends, hill/ dips in the road, parked vehicles, hedges etc)?				x	
TSM.9	Will the site be safe during hours of darkness and adverse weather conditions?			X		
TSM.10	Is the carriageway/footway being kept clear of mud and surplus equipment?				x	
TSM.11	Are materials/plant correctly and safely stored?	x				
TSM.12	Is there safe access/egress to adjacent private premises and local roads/junctions?	x				
TSM.13	Does signing and guarding meet the changing site conditions?	x				
TSM.14	Are traffic control arrangements working at their optimum level to reduce traffic delays?				x	
TSM.15	Are all misleading permanent signs & road markings covered? Have all signs been positioned correctly to eliminate a potential hazard to the general public?				x	
TSM.16	Have the needs of pedestrians and other vulnerable road users (disabled pedestrians, blind, cyclists, horses etc) been addressed in the layout? If existing public routes have been blocked, has suitable alternatives been provided?				x	
TSM.17	Is the Work Area clearly defined to the road user?				x	



Photo TSM 1 - 1200mm 'Roadworks Ahead' signage with supplementary plate.

Photo TSM 2 - 1200mm 'Offside Lane Closed' signage with supplementary plate. TM ahead tranfers fast lane to slow lane(fast lane and hard shoulder closed) and then slow lane to fast lane (hard shoulder and slow lane closed) prior to Junction 13.

Photo TSM 3 - 1200mm 'Offside Lane Closed' signage with supplementary plate.

Photo TSM 4 - 1200mm 'Offside Lane Closed' signage with supplementary plate. Plate colour not in accordance with P001 (refer to Table 8.2.2 of Chapter 8)

Photo TSM 5 - 1200mm 'Offside Lane Closed' signage with supplementary plate.

Photo TSM 6 - 'End of Hard Shoulder' supplementary plate. Note 100m distance plate on verge.

Photo TSM 7 - Advance warning of hard shoulder closure and commencement of fast lane taper. No lamps to taper. This location is unlit. Does not comply with the recommendations of Table 8.3.5, paragraph 8.2.5.6 and paragraph 8.2.8.3 of Chapter 8.

Photo TSM 8 - Hard shoulder taper. Cones in taper appear to be approx. 3m c/c. Table 8.3.5 of Chapter 8 recommends 1.5m c/c.



GOOD and BAD Practices



Bad Practice



•No Reflective markings or signage on truck

- Insufficient cones
- •No Safe Zone
- •No pre-warning







•Good Reflective markings on vehicle

•Cones well defined and deliniated

•Safe Zone







•Clear layout

•Reflectors on cones




Bad Practices



Conflicting signage
No Alternative Route indicated
Sign on non-reflective board







Insufficient Definition




Bad Practices



•Old lining not removed



Bad Practices



•Inadequate signage

- •No delineation
- •Road markings on new section visible to motorist







How it should be done!!



Bad Practices



•100km/h sign not covered in middle of roadwork's

•Advertisement within confines of roadworks



Good Practice



Fenced parking area created for operatives. Side road left clear from parked vehicles. Common hazard removed.









ARUP

Temporary Safety Measures Inspections

THANK YOU

ANY QUESTIONS??

National Roads Authority - Standards Section Training for New Developments April 2013

