

Effective Bridge Management

Area Engineers March 2014

Liam Duffy - National Roads Authority

Overview

- Introduction
- Inspection types
- Factors affecting bridge durability
- Bridge Defects
- Structural Capacity Assessments
- Repairs and Strengthening


Long Life Bridges: Adare Bridge Co. Limerick




Irish Stone Bridges (O’Keeffe and Simington): “...*there is no reason to dispute the date range 1390-1410...*”

Irish Stone Bridges (O’Keeffe and Simington): “...*Richly mantled with ivy, this ancient Bridge is very picturesque, blending as it were with the ivy-clad walls of the castle...*”

Effective Bridge Management





CUMBRIA FLOODS

ENGINEERS IN THE FRONT LINE AS VITAL INFRASTRUCTURE IS KNOCKED OUT

News

Minneapolis bridge collapse exposes inspection failures

INADEQUATE INSPECTION regimes failed to expose functional and catastrophic structural weaknesses in Minneapolis' devastated I-35W bridge, structural specialists said this week.

The 1,357m bridge across the Mississippi river at Minneapolis in Minnesota collapsed without warning at 18:00 local time last Wednesday, killing five and leaving a further eight unaccounted for.

Fatigue in the structure's girders is now thought to be the main focus of the investigation by the federal National Transportation Safety Board (NTSB), now in full swing.

It is currently carrying out a detailed finite element analysis of the bridge to help assess possible scenarios.

Minnesota's State Department of Transport (MNDOT) this week confirmed that several inspections of the bridge relied on "visual inspections with load tests and strain gauges".

A spokesman said no intrusive tests were carried out.

But according to Michael Patsios, structural technical director, Donald Peterson-Risk visual inspections with strain gauges carried out on I-35W, would have missed crucial details. He recently led inspection teams in the United States with Peter Blumhertz.

"As well as looking, you have to do some testing with some intrusive work, to get a much better picture," said Peterson-Risk.

"If something looks good, it might not always be so. Similarly, there are times when they look bad but are OK."

He said that with steel bridges, small fractures could be made



and strain gauges installed to give engineers a better picture of precisely what was happening inside the structure.

The bridge was a three span steel truss built in 1977. It had longitudinally split a concrete slab deck and was known to have no structural redundancy.

According to a recent report by consultant URS, written in 2006 it had 52 "structure critical" transverse members along the 1.07km span and two 81mm side spans (see page 4). The report also criticised the inspection regime for the structure.

MNDOT this week confirmed



the MNDOT was less strict than it conducted inspections annually, while federal law required biennial inspections.

The bridge was also undergoing non-structural remediation and joint replacement work at the time of the collapse.

Although it was known to have been suffering severe fatigue cracks it is understood that work may have also contributed to the collapse.

Structuring work closed two of the four lanes in each direction, but asymmetrically across the bridge while concrete deck sections were replaced.

Bridge expert Mark Whitty said this "would give some increasing stresses in the two trusses - one going one way, the other the other way, and some strain in the cross-members".

Another UK based structural engineer who wishes to remain anonymous added: "The deck replacement work may have damaged a critical member of the truss. If there was a fatigue crack, who knows they may have taken a piece of deck out above a fatigue crack, put a jack beam on it and left it off".

He added: "It only needs one member in one truss to go for the whole thing to come down - truss bridges not generally have any redundancy".

Bentley chairman Mark Bates, said that the collapse is consistent with fatigue in the steel members.

"Fatigue always starts slowly, but you're not going to find anything before anything begins failing," he said. "Most fatigue failures are preceded by visible cracks, but it is possible the crack length is small or invisible to the naked eye."

Ed Owen in Minneapolis

For more on NCE's top stories visit www.nceplus.co.uk

News

Network Rail was praised by the Office of Rail Regulation last week for reducing train delays on the national network. But it was warned that it must do more at regional and local levels. The rail regulator's third annual report on the rail operator also reveals that Network Rail has failed to meet all of its health and safety targets

Poor maintenance blamed for Montreal collapse

SALI CORBERON of steel reinforcement in the deck of a road bridge in Montreal is the likely cause of a collapse which killed five people on Saturday, engineers said this week.

Heavy road salting, required during Canadian winters, was thought to have created a corrosive cocktail that easily penetrated the movement joint where the road deck slab met the cantilever supports - an acknowledged weak spot (see page 4).

Montrealis contacted emergency services at around 11am last Saturday, as chunks of concrete fell onto the highway from the overpass.


A spokeswoman for highway authority Transport Québec, confirmed that a highway patrol arrived at the scene before midday, made a visual inspection, but did not conduct a full survey of the structure.

The patrol also assumed that the falling concrete was not a structural threat and declared that the bridge did not need to close.

The details continued to fall and at around 12:00pm the structure collapsed. Witnesses said that light traffic prevented further loss of life.

"The inspection was not adequate. We need to know what sort of inspection was carried out, what sort of inspection would have been adequate, and how prevalent is this fault," said Dr Ghani Rahman, chair of civil engineering at Canada's McMaster University.

The bridge was a half joint deck structure comprising two short cantilever spans supporting the bridge's central span on either side. The central span is simply supported




The "flawed" half joint deck structure is no longer used in the UK or Canada

between bearings on the side cantilevers.

Engineers explained that the most likely cause of failure was salt corrosion over time. This would have led to reinforcement deterioration which would then have caused a shear failure of the concrete from the joint to the point of contact with the support.

"Corrosion does salt is causing havoc on both concrete and steel. On this bridge there would have been the release of oxygen from the steel. In addition there would have been accidental chemical spills, seeping into the con-



Bridges on the NRA Network

- Almost 3,000 structures on NP & NS network > 2.0m span
- 60% Concrete, 27% Masonry, 8% Steel
- Not responsible for managing PPP bridges although we monitor the Concessionaire's management of bridges
- MMarC Contractors responsible for RM for bridges on their networks & NRA manage structural work



Eirspan Database

- New desktop version of database for Regional Road bridges will issue to LAs next month from NRA IT
- Existing data requires converting by NRA IT
- Booklet with screenshots from database explaining data transfer etc.
- New web-based version for NRA bridges

Inspection Types

- Routine Inspection
 - Previously an annual inspection by LAs
 - Engage consultants now
- Principal Inspection
 - Structural inspection by experienced bridge engineers
 - Interval 1-6 years
- Special Inspection
 - Defect investigation, underwater inspection, assessment

Routine inspection and maintenance



Vegetation clearance prevents stonework deterioration,
debris clearance from watercourses prevents scour damage

Scour Damage & Scour Susceptibility

Scour:

- Debris build-up must be cleared when found
- BD97/12 Assessment of scour at highway bridges
- CIRIA C551 Manual on scour at bridges and other hydraulic structures



PI – Inspect difficult access components



Special Inspection - Youghal Bridge

PTSI Phase 3 Inspection



Factors affecting durability



Leaking expansion joint or failed waterproofing. Modern construction of integral bridges where possible.



Waterproofing Application & Testing



14 Aug 2004 14:11

29 Aug 2004 15:48

Bridge Inspector Decisions – RC Defects



- BA 35/90 Inspection and repair of concrete highway structures
- CBDG Technical Guide 2: Testing & monitoring the durability of concrete structures



Leenane Bridge collapse



Build-up of debris at bridge following rainfall which exceeded 1/100yr return

Bridge Inspector Decisions – Parapet Damage



Is the failure mode of these parapets correct?
Inspector to check for cracked posts



Bridge Inspector Decisions –Steel Defects




BD12 includes for concrete invert to prevent such corrosion.

Plate Girder corrosion

Structure Work Types and Numbers

Structure Work Types and Numbers



Issues to Consider Before Repair

- Condition rating & likely rate of deterioration
- Durability
- Structural capacity – assessment should be considered before significant repairs. Assess using BD21/01, BA16/97, etc for structures designed pre-BS5400.
- If bridge fails assessment, strengthening may be required
- No link between condition rating & assessed capacity
- Whole life cost – is it better to undertake cyclical concrete repairs to a slab soffit or replace the deck?

Assessments



Coring to determine arch barrel depth



Rare example of failure under load

Repair historic structures sympathetically



New NRA Specification Series 2400. Lime mortar 1part NHL5 to 2.5 parts well-graded sand, full joints, stonework to match existing

Bridge Management Issue - Services




Poor Aesthetics, Durability Issues



Expansion Joint Awareness



12 Sep 2009 13:09



Masonry arch construction



